

Occurrence Communication: Oc00065-2020**Date:** 04/Mar/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145906
Marks: N922AE	Operator: ENVOY	Occurrence Date: 20/Sep/2019
Ata: 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: JACKSONVILLE INTL - JACKSONVILLE - FL - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of smoke in the cockpit
SMOKE IN FLIGHT DECK LEVEL AT FL250 DIVR JAX ACCT SMOKE IN COCKPIT. EMER DECL. C/A-
PERFORMED FIM TASK 21-20-00-810-801-A AND FOUND PACK 1 ACM NOT CYCLING PROPERLY. REF
ITEM 2 THIS LG PG FOR PACK 1 DEFERRAL AND PERFORMED ETN-EM-72-034.