

Occurrence Communication: Oc00078-2020**Date:** 17/Mar/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 XR	Serial Number: 145914
Marks: N16183	Operator: COMMUTAIR	Occurrence Date: 12/Mar/2020
Ata: 36	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of smoke in the cockpit
The flight crew reported smoke in the cockpit during climb out.

Maintenance personnel noticed smoke during engine 1 shot down while troubleshooting LPT shaft o-ring. No further defects were noted.