

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00138-2020 Date: 11/Aug/2020 Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145150
Marks:	Operator:	Occurence Date:
N634AE	PIEDMONT AIRLINES	10/Aug/2020
Ata: 00	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: ROANOKE REGL/WOODRUM - ROANOKE - VA - UNITED STATES		
Injuries: X None Light:	0 Serious: 0	Fatal: ⁰

Occurence Description:

Report of rejected takeoff due to smoke in the cockpit

It was reported that the aircraft, with 36 people on board, was accelerating when the flight crew decided to reject the takeoff at high speed reporting smoke in the cockpit. The aircraft stopped on the runway and was evacuated. No injuries were reported.