

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00146-2020 Date: 18/Aug/2020 Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 LR	145558
<b>Marks:</b> N26545	Operator: EXPRESSJET	Occurence Date: 29/Nov/2019
<b>Ata</b> : 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: X None Light:	0 Serious: 0 Fatal:	0
Description 1		

## **Occurence Description:**

STRONG ELECTRICAL ODOR IN COCKPIT.

PILOT REPORTED STRONG ELECTRICAL ODOR IN COCKPIT LASTED SEVERAL MINUTES AND CLEARED. FLIGHT ATTENDANT REPORTED "HAZE" IN CABIN ALSO LASTING SEVERAL MINUTES.

ADDITIONAL INFORMATION:

ITEM MOVED TO MEL #21-51-00-3. ON 04DEC2019 MAINTENANCE REPLACED #1 PACK AIR CICLE MACHINE WITH OPERATIONAL CHECK GOOD. AIRCRAFT WAS APPROVED FOR RETURN TO SERVICE.