

**EMBRAER S.A.**

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901
Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00158-2020 **Date:** 09/Sep/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145115
Marks: N625AE	Operator: PIEDMONT AIRLINES	Occurrence Date: 14/Aug/2020
Ata: 72	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of smoke in the cabin and cockpit during takeoff
White smoke was reported in the cabin and cockpit during takeoff.

Maintenance personnel inspected the engines and found oil in the compressor flow path extension from the front sump.