


|                                                                                                                                                |                                                                                                                                  |                                                                   |
|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
|  <p><b>SOUTH AFRICAN<br/>CIVIL AVIATION<br/>AUTHORITY</b></p> | <p><b>REPUBLIC OF SOUTH AFRICA</b></p> <p><b>CIVIL AVIATION AUTHORITY</b></p> <p>Private Bag x 73<br/>Halfway House<br/>1685</p> | <p><b>AIP<br/>SUPPLEMENT<br/>S110/24<br/>26 DECEMBER 2024</b></p> |
| <p>Tel: +27 860 267 435<br/>E-Mail: <a href="mailto:Clientcare@caa.co.za">Clientcare@caa.co.za</a></p>                                         |                                                                                                                                  |                                                                   |

**JOHANNESBURG FLIGHT INFORMATION REGION (FAJA)**

**AERODROME, AERODROME SERVICES AND FACILITIES STATUS**

**MARGATE AERODROME (FAMG)**

*This supplement replaces S043/24.*

*Validity Period: 26 December 2024 – 11 June 2025*

1. *NIL MET EQPT AVBL.*
2. *ALL RWY LGT U/S. NIL NGT FLY PERMITTED.*
3. *PAPI RWY 05/23 U/S.*
4. *NIL AFIS 122.70 MHZ AVBL.*
5. *NIL OBST LGT ON APN FLOOD LIGHTS (85FT AGL).*
6. *NIL OBST LGT ON TWR (82FT AGL).*
7. *WINDSOCK (305131S 0302035E) (6M AGL) OBST LGT U/S.*
8. *UNMARKED WIRE FENCE (3M AGL) ERECTED WI TECHNICAL AREA AT LIGHT PLANE CLUB. ADJ TO HLDG POINT RWY 05 BTN TWY FENCE AND FIRST HANGAR.*
9. *NIL FUEL AVBL.*

*Note: Changes to this SUP will be issued via a NOTAM.*

*NOTAM originators remain responsible for any update to this supplement. ATSU will contact the AIP department on [aim@atns.co.za](mailto:aim@atns.co.za). Other NOTAM originators to contact the SACAA AIS office on [venterl@caa.co.za](mailto:venterl@caa.co.za), [pitsot@caa.co.za](mailto:pitsot@caa.co.za), [nkosiv@caa.co.za](mailto:nkosiv@caa.co.za) and [khumalog@caa.co.za](mailto:khumalog@caa.co.za).*