SOUTH AFRICAN



Aircraft Occurrences August 2017

Statistics reflect accident information entered into the computer by the Accident and Investigation Office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

Accident ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Circumstances	Type of Operation
CA18/2/3/9634	05 August 17	Bushbaby	ZU-EKL	WC	GPS coordinates S 33°44'58.63" E 018°33'7.87"	0	During flight, the aircraft engine cut off and the pilot attempted a forced landing on an open field. After touched down, the nose wheel collapsed and the aircraft flipped over.	Private flight
CA18/2/3/9636	11 August 17	R44 Raven II	ZS-HLM	LIMPOPO	GPS coordinates S 23°040.17" E 027°15 49.62"	0	During flight, the helicopter collided with the powerlines.	Commercial flight
CA18/2/3/9637	15 August 17	Cessna C210	ZS-MBU	GP	Wonderboom Aerodrome	0	The pilot stated that on short finals, he experienced an engine failure.	Test flight
CA/3/2/1172	18 August 17	AVRO 146- RJ85A	ZS-ASZ	wc	Approximately R330,9DME CTV	0	The pilot declared an emergency that the number four engine was on fire.	Commercial flight

083 461 4887

aiidinbox@caa.co.za Last date of update: 03 September 2017