



Aircraft Occurrences May 2020

Statistical information entered into the computer by the Accident and Investigation Office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

| Accident ref | Date of Occ | Aircraft Type | Registration | Province | Area of Occurrence | Fatalities | Circumstances | Type of operation |
|--------------|-------------|----------------------|--------------|----------|---|------------|---|---|
| TBU | 30 May 2020 | Robinson R44 | ZS-RYU | EC | 31°34'33.00" South 026°03'50.60" East, elevation 4 460 feet AMSL | 0 | According to a telephone conversation with the pilot he indicated that he was accompanied by a passenger while conducting game counting of Springbok antelope on a Government owned farm with the intention of culling to be conducted. | General Aviation and Operating Flight Rules (Part 91) |
| TBU | 20 May 2020 | Skyliner 600 Z226 | ZU-TAM | GP | FAKR | 0 | The pilot reported that during final approach runway 08 the landing gear was down with three green indication. During touch down the landing gear collapsed. The aircraft skid for 20m before stopping on the runway and the pilot and passenger disembarked. | Operation of Non-type Certified Aircraft (Part 94) |

083 461 4887

aiidinbox@caa.co.za

Last date of update: 04 June 2020