



1. View taken along approximate line of flight towards the left of the mountain, showing :
A. Blood pool where Non-European was struck
B. Scattered remains of bicycle
C. Main wreckage



2. View taken along approximate line of flight towards the left of the mountain, showing :
A. Blood pool where Non-European was struck
B. Scattered remains of bicycle



3. View along line of flight :
A. Hat placed at wheel tracks on ground - first point of impact




4. View towards main wreckage from :
A. First point of impact by port mainplane tip
B. Hole in ground caused by nose digging in



1. View taken along approximate line of flight towards the left of the mountain, showing :
A. Blood pool where Non-European was struck
B. Scattered remains of bicycle
C. Main wreckage



2. View taken along approximate line of flight towards the left of the mountain, showing :
A. Blood pool where Non-European was struck
B. Scattered remains of bicycle



3. View along line of flight :
A. Hat placed at wheel tracks on ground - first point of impact



4. View towards main wreckage from :
A. First point of impact by port mainplane tip
B. Hole in ground caused by nose digging in

7

ZS - DHA. PIPER TRI-PACER.
VAN RHYNSDORP - 20 JUNE 1953



5. Main wreckage showing crumpled port mainplane
and fire damage to starboard mainplane