

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **EAD** 2014-0215-E - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2017-0028-E

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2014-0215-E>

* **AD** 2016-0112 - AIRBUS: SUPERSEDED BY EASA AD 2017-0029

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0112>

* **AD** 2016-0111 - AIRBUS: SUPERSEDED BY EASA AD 2017-0027

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0111>

* **AD** 2017-0030 - AIRBUS: Time Limits / Maintenance Checks – System Equipment Maintenance Requirements – ALS Part 4 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0030>

* **AD** 2017-0029 - AIRBUS: Time Limits / Maintenance Checks – Certification Maintenance Requirements - ALS Part 3 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0029>

* **AD** 2017-0027 - AIRBUS: Time Limits / Maintenance Checks – Damage Tolerant Airworthiness Limitation Items – ALS Part 2 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0027>

* **PAD** 17-021R1 - AIRBUS: Fuel – Fuel Pump Canister Hood – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/17-021R1>

* **AD** US-2017-02-03 - BOEING: Water / Waste - Spray Shield - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-02-03>

* **EAD** 2017-0028-E - LEONARDO S.p.A. HELICOPTERS: Main Rotor – Rotating Scissors – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0028-E>

* **AD** US-2017-02-10 - BOEING: Fuselage - Skin at Body Station 540 Bulkhead Chords - Inspection / Modification / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-02-10>