

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2016-0107** - AIRBUS: SUPERSEDED BY EASA AD 2018-0064

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0107>

* **AD DCA-750XL-24A** - PACIFIC AEROSPACE LTD: Pitot Static Tube Support Clamps - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/DCA-750XL-24A>

* **AD 2018-0067** - ENSTROM HELICOPTER CORPORATION: Main Rotor – Hydraulic Damper / Belt Tension Shaft Rod End Assembly – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0067>

* **AD 2018-0064** - AIRBUS: Hydraulic Power – Hydraulic Reservoir Pressure Relief Valve – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0064>

* **AD 2018-0041R1** - AIRBUS: Engine – Operational Restrictions

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0041R1>

* **AD DCA-750XL-25A** - PACIFIC AEROSPACE LTD: Wing Leading Edge Tank Abrasion - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/DCA-750XL-25A>

* **AD US-2018-04-08** - BOEING: Fuselage - Gore Webs, Gore Web Lap Splices and Repair Webs of the Aft Pressure Bulkhead - Repetitive Inspections

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-04-08>

* **AD 2018-0065** - AIRBUS HELICOPTERS: Time Limits / Maintenance Checks – Main Gearbox / Particle Detectors – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0065>

* **AD 2018-0066** - AIRBUS HELICOPTERS: Time Limits / Maintenance Checks – Main Gearbox / Particle Detectors – Inspection Main Rotor Drive – Planet Gear Assemblies – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0066>

* **AD DCA-750XL-28** - PACIFIC AEROSPACE LTD: Elevator Bellcrank Pivot - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/DCA-750XL-28>