The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** US-2018-02-05 - PIPER AIRCRAFT INC.: Placard and Markings - Fuel Tank Selector Cover - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/US-2018-02-05

* **PAD** 18-045 - AIRBUS HELICOPTERS: Fuselage – Tail Boom / Fenestron Junction Frame – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/18-045

* **AD** 2018-0070 - WSK PZL - SWIDNIK S.A.: Main Rotor – Vibration Absorber Star – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0070

* PAD 18-046 - AIRBUS: Nacelles / Pylons – Inner J-Ring and V-Groove Interface – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/18-046