Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** US-2019-07-02 - ROBINSON HELICOPTER COMPANY: Engine Oil Storage - Oil Tank Outlet's Fitting Color - Inspection

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/US-2019-07-02</u>